

SCAN MARINE/WALLAS Service Bulletin 070703

July 3, 2007

Re: Wallas 85DU heat indicator plug installation.

The Wallas 85DU comes fully assembled with all wiring connections made up as part of the final assembly process. Sometimes during stove installation, with or without the 270 lid, the green connector to the heat indicator lamp at the front of the stove gets jarred partially or completely loose. Please see the picture, below.

If this connection is incorrect, the stove may run, but not respond to the shut down command, it may run erratically or not run at all. Simply push the plug back into place before running the unit again. As a normal part of any troubleshooting process, please verify ALL electrical connections are made up properly.



This problem should be limited to the 85DU, but check this connection if you experience any of the above symptoms on your 85DP as well.