

SCAN MARINE/WALLAS Service Bulletin 070601

June 15, 2007

Re: Wallas 270 blower lid (fits Wallas 85DU and 85DP units) cable connection.

The Wallas 270 blower lid assembly is supplied in two primary parts:

1. The blower assembly, which the user or boat builder will assemble to the stove itself.
2. The lid assembly which mounts to the stove/blower assembly after the stove/blower assembly has been mounted into the boat.

The blower assembly connects to the stove using a 10" to 12" wire harness, terminating in a small, square latching plug. The lid assembly connects electrically to the stove/blower using a similar but shorter harness that terminates in the same kind of square, latching plug. This can be seen at the back left side of the lid when it is in place.

In both cases, it is important that these plugs are installed properly, with the plug indexed properly so the latch hooks over the corresponding hook on the female receiver. If forced, these plugs can be inserted incorrectly, which will cause the stove either to not operate or to operate erratically. Failure to plug either plug into place will cause the stove not to operate.

